The 10kV bus voltage is too high



Overview

DC Bus Overvoltage White Paper Numerous built-in protections and fault indications are provided with modern VFDs, including the commonly seen DC Bus Overvo.

Key Takeaways

High 10kV bus voltage can result from supply overvoltage, regenerative energy from motors, harmonics, or faulty PT cabinet fuses, and requires careful inspection and corrective measures. Understanding 10kV Bus VoltageA bus is a shared conductor that distributes electrical power to multiple components in a system. The 10kV bus voltage represents the electrical potential on this main conductor in medium-voltage distribution networks.

Maintaining stable bus voltage is critical for reliable operation of connected loads and protection devices.

Common Causes of High Bus Voltage

Incoming Line Overvoltage: If the supply voltage from the upstream network is higher than nominal, the bus voltage will rise accordingly. Regenerative Energy from Motors: High-inertia loads or rapid deceleration of motors can feed energy back into the bus, causing voltage spikes. Harmonics in Supply Power: Electrical noise or harmonics can artificially elevate the measured bus voltage.

Faulty P

T Cabinet Fuses: Poor internal contact in potential transformer (PT) cabinet fuses can cause irregular voltage fluctuations, sometimes appearing as high voltage. Mechanical or Insulation Issues: Busbar discharge, insulator damage, or loose connections can lead to voltage instability and localized overvoltage.

© 2026 FD SOLUCIONES OPTICAL SYSTEMS - All rights reserved

Troubleshooting and Corrective Actions

Inspect P

T Cabinet Fuses: Check for poor contact or intermittent operation, which can cause voltage spikes. Check Busbar Connections and Insulators: Use infrared thermography to detect overheating at joints and visually inspect for flashover marks. Verify Incoming Supply Voltage: Ensure upstream voltage is within specification and harmonics are minimized.

Motor and Load Management: Adjust deceleration times for high-inertia motors to prevent regenerative overvoltage. Protection Device Settings: Confirm relay and protection settings are correct to avoid unnecessary tripping or misoperation.

Preventive Measures

Regular maintenance of busbar joints, fuses, and insulators. Installation of surge arresters or voltage-limiting devices. Monitoring systems to detect voltage fluctuations early.

Proper coordination of reactive power compensation devices to avoid frequent switching due to voltage spikes. By systematically inspecting the bus system, PT cabinet, and connected loads, high 10kV bus voltage can be diagnosed and mitigated, ensuring safe and stable operation of the medium-voltage network.

Article Content

DC Bus Overvoltage White Paper

Numerous built-in protections and fault indications are provided with modern VFDs, including the commonly seen DC Bus Overvoltage Fault. This fault has several possible causes and this

Regenerative Drive Failures: How to Fix DC Bus Overvoltage

Once you''ve identified where the excess voltage is coming from, you can dial into fixing it. The solution could be as simple as reconfiguring your drive parameters.

The voltage of the 10kV bus fluctuates between high and low, and the ...

After three days of investigation, the root cause of the malfunction was finally discovered - a high-voltage fuse in the PT cabinet that appeared to be normal but had poor internal contact.

What Is Bus Voltage and How Does It Work?

© 2026 FD SOLUCIONES OPTICAL SYSTEMS - All rights reserved

If a high-speed conveyor belt decelerates too quickly, the motor acts as a generator and feeds energy back into the DC bus, causing the voltage to spike. The fix can be as simple as

BUS Voltage Fault

If the frequency is higher, update the inverter firmware to the latest version. 2 eck if the PV panel voltage exceeds the MPPT range. If the voltage is too high, it is recommended to reduce the number

DC bus overvoltage fault on SURT10000XLI

I''ve checked the high voltage relays and all appear to be proper continuity and impedance across the coil. The unit seems to run on batteries OK - just happens when mains are

Bus Voltage Fault

Use a multimeter to measure the voltage at each MPPT, make sure that the Max. PV input voltage in Datasheet is not exceeded.If the measured voltage value is close to the maximum MPPT range

Solution Square : Troubleshooting an Over-voltage Trip (OVT)

An Over-Voltage trip (OVT or OUT) occurs when the DC bus voltage exceeds the maximum allowable level. This can be caused by a number of conditions therefore it is

Understanding the Causes and Effects of Bus Overvoltage in Electrical ...

Overvoltage in bus systems is a pretty serious issue — it can cause some major disruptions in electrical setups, impacting equipment performance and even shortening their lifespan.

EG46000XP bus volage too high fault

I have a problem where I keep getting intermittent fault 19 (bus voltage too high). I measured the 2 PV inputs and they are 358vdc consistently. I set the parameter to use 2 separate

Bus Overvoltage Faults: How to Resist

This too will be covered in the Installation Manual. Regen. Yet another way to “Dot your I''s and cross your T''s” when quoting a job or designing your machine. Doing it right, prior to

Overbraking / High DC Bus Voltage Fault on Drive

© 2026 FD SOLUCIONES OPTICAL SYSTEMS - All rights reserved

I have a 600V 250hp drive that sometimes trips on "Overbraking", when requested to run. This fault occurs when the DC bus voltage reaches 1174V. The same motor has caused this fault

Troubleshooting VFD Problems – Overvoltage Fault

Also read- How to measure DC bus voltage and DC bus voltage ripple For large HP drives, medium voltage (high voltage) drives, there could be

Thoughts and questions about the "High Voltage DC Bus" inside of

To prevent a "HV DC Bus too high" error, the inverter should always be running and should have at least a bit of load to "consume" energy from the HV DC Bus to prevent it from over

VFD DC Bus Overvoltage Maintenance Recommendations

Discover the essential maintenance actions to take after a Variable Frequency Drive (VFD) experiences a DC bus overvoltage event, including event log review, visual inspection,

OV-BUS: DC bus overvoltage

Possible causes Excessive solar panel voltage: The solar panels might be generating more voltage than the inverter can handle, especially in conditions of high irradiance or low temperature. Incorrect

Fault code 8 (bus over voltage) for second eg4 6000ex

When I turned it all on, though, the original inverter is working fine but the new inverter came on then started screaming and displayed fault 8, which the manual labels "Bus voltage too

Bus Voltage High

My EG4 18Kpv has twice now gave me a fault of Bus Voltage High while using a leaf blower, shut my system down and started my backup generator any suggestions would be appreciated

© 2026 FD SOLUCIONES OPTICAL SYSTEMS - All rights reserved

Contact Us

Continue your research online:

Website: https://fdsoluciones.es
Technical inquiry: https://fdsoluciones.es/project-enquiry.html

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 FD SOLUCIONES OPTICAL SYSTEMS - All rights reserved